00862.023431 <u>PATENT</u>

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
	:	Examiner: Shelby L. Fidler
YOSUKE USHIGOME	)	
	:	Group Art Unit: 2861
Appl. No.: 10/765,857	)	
	:	Confirmation No.: 2621
Filed: January 29, 2004	)	
	:	
For: BATTERY RESIDUAL CAPACITY	)	
DETECTION METHOD AND PRINTING	:	
APPARATUS USING THE METHOD	)	
	:	
U.S. Patent No.: 7,052,105 B2	)	
	:	
Issued: May 30, 2006	)	January 15, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form is enclosed.

The statutory fee of \$100.00 to cover such Certificate of Correction is being paid electronically.

Patentee's undersigned attorney may be reached in our Washington, D.C.

office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson Attorney for Patentee Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800

Facsimile: (212) 218-2200

MAW:eyw

Form #33 - 2 -

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 7,052,105 B2

**DATED** : May 30, 2006

INVENTOR(S): USHIGOME Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## COLUMN 4:

Line 16, "ink-jet" should read --inkjet--.

## COLUMN 5:

Line 3, "includes" should read --include--.

#### COLUMN 6:

Line 55, "pickup" (2<sup>nd</sup> occurrence) should read --pick up--.

#### COLUMN 8:

Line 50, "block **10**," should read --block **10**;--.

# COLUMN 11:

Line 17, "FIG. 6," should read --FIG. 6;--.

# COLUMN 13:

Line 3, "ensured," should read --ensured;--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DC\_Main 257751 v1 PATENT NO. <u>US 7,052,105 B2</u>

No. of add'l. copies @ 30¢ per page



# Staple Here Only! SINI SINI SINI BEINI BEI

# UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

**PATENT NO.** : US 7,052,105 B2

**DATED** : May 30, 2006

INVENTOR(S): USHIGOME Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 14:

Line 3, "ink-jet" should read --inkjet--.

Line 10, "a continuous" should read --continuous--.

Line 34, "printhead," should read --printhead;--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2100 - Telephole (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DC\_Main 257751 v1 PATENT NO. <u>US 7,052,105 B2</u>

No. of add'l. copies @ 30¢ per page

